

Land Rover Discovery Sport 2.0d Se 7-seater


[View Car](#)

Inspector: Loh Wei Chen


Date of Inspection: 29th April 2024

Plate No. (Sell with/Sell without).	Sell With	Brand	Land Rover
Model	Discovery	Sub Model	Sport 2.0d Se 7-seater
Color	Brown	Manufactured Year	2017
Transmission	Automatic	Fuel type	Diesel
Registration Card	New	Registration Type	Company
Registration Date	2017-07-31	Engine Capacity	1999
Mileage	130000	Seat Number	7
No. of previous Owner	4	Service Book/Sticker	Yes
No. of Keys	1		


CARRO Certified




160-Point Inspection




5-Day Money Back Guarantee



12-Month Warranty for Engine & Gearbox






No Mileage Tampering







No Major Accidents, Fire & Flood Damage

Inspection Checklist

Inspector: Loh Wei Chen

 131 Pass	 0 Rectified	 24 To Be Rectified	N/A 9 Not Applicable
--	---	--	----------------------

Road Test Checks

Items	Status	Comments	Items	Status	Comments
Engine Starts Properly			Engine Noise		abnormal noise
Engine Idles Properly			Engine Acceleration		

Belting	!	belting crack	Engine & Transmission Mounting	✓	
Brake Pad Thickness	!	rear brake pads less than 5mm	Brake Pedal	✓	
Brake Lines, Hoses & Fittings	✓		Suspension and Shock absorber	!	rear absorber worn
Steering Operation	✓		Undercarriage Noises	!	splash cover damage
Gear Box	✓		Clutch Operates Properly	✓	
Gauges Operate properly	✓		Transmission / Transaxle Shift	✓	
Tranmission/ Transaxle Noise	✓		4X4 Operation	✓	
Drive Axle / Transfer Case Noise	✓		No Major Accident	✓	
No Fire Damage	✓		No Flood Damage	✓	

Exterior

Exterior Images



Items	Status	Comments		Status	Comments
Door Seals (All Doors)	✓		Door Handles	✓	
Front Bumper	✓	Scratches	Front Fender (Left)	✓	
Front Doors (Right)	!	Scratches	Front Door Panel (Right)	!	scratches

Front Doors (Left)		Dented	Front Door Panel (Left)		dented
Front Bonnet, Support and Insulator		Scratches	Front Fender (Right)		
Rear Bonnet			Rear Fender / Quarterpanel (Right)		
Rear Fender / Quarterpanel (Left)		discoloration	Rear Bumper		Scratches
Rear Doors (Right)		Scratches	Rear Door Panel (Right)		scratches
Rear Doors (Left)		Scratches	Rear Door Panel (Left)		scratches
Side Skirt (Left)			Side Skirt (Right)		
Body Panel Inspection			Grille Inspection		paint peel out
Sunroof / Moonroof	N/A		Convertible Top	N/A	
Front Bonnet Release			Front Windscreen		
Rear Windscreen			Front Window (Left)		
Front Window (Right)			Rear Window (Right)		
Rear Window (Left)			Rear Quarter Window (Left)		
Rear Quarter Window (Right)			Rear Window Wiper Switch		
Windscreen Wipers Switch			Wiper Blades Front & Rear		
Power Window Controls			Left Side Mirror		
Right Side Mirror		scratches	Outside Rear View Mirrors		
Sun Visors, Vanity Mirror & Light			Front End Exterior Lights (Left) - Headlight		
Front End Exterior Lights (Right) - Headlight		scratches	Side Exterior Lights		
Rear End Exterior Lights (Left) - Reverse, Taillamp, Stop			Rear End Exterior Lights (Right) - Reverse, Taillamp, Stop		

Hazard Lights			Indicator Light		
Fog Lamp Function	N/A		Daytime Running Light		
Low / High Beam Function			Auto On / Off Lights		
Spare Tyre			Jack & Tool Kit		
Rims		scratches	Wheel Alignment		
Wheel Covers & Center Caps					

Interior

Items	Status	Comments		Status	Comments
Radio / Cassette / CD / DVD Player			Speakers		
Alarm / Theft Deterrent System			Reverse Camera		
Antenna			Air Conditioning Switch Panel		
Air Conditioning Parts			Air Conditioning System		
Front Aircon Vents			Rear Aircon Vents		
Anti - Fog / Defroster Coil Damage			Center Armrest / Console		
Floor Mats			Interior Carpet		
Front Door Trim Board (Right)			Front Door Trim Board (Left)		
Door Trim Board 2nd Row (Right)			Door Trim Board 2nd Row (Left)		interior door trim handle loose
A - Pillar Door Trim Board (Right)			A - Pillar Door Trim Board (Left)		
B - Pillar Door Trim Board (Right)			B - Pillar Door Trim Board (Left)		
C - Pillar Door Trim Board (Right)			C - Pillar Door Trim Board (Left)		

Glove Box	✓		Dashboard Drawer	N/A	
Front Seat Including Electric Seat	✓		Rear Seat Including Electric Seat	N/A	
Folding Seats	✓		Hot / Warmed Seats	N/A	
Cooled Seats	N/A		Seat & Head Restraint Adjustment	✓	
Headlining	!	drop	Parcel Shelf / Speaker Board / Tonneau Cover	✓	
Clock	✓		Power Outlet - 12 V Port / Cigarette Lighter	✓	
Power Outlet - USB Port / Cigarette Lighter	✓		Power Steering	✓	
Steering Wheel Controls	✓	peel out	Steering Wheel Condition	✓	
Tilt / Telescopic Steering Wheel	✓		Tripmeter And Odometer	✓	
Interior Courtesy, Dome & Map Lights	✓		Ashtrays	N/A	
Handbrake / Footbrake Lever	✓		Gear Knob	✓	
Horn	✓		Warning Light	!	DTC present
Cruise Control Operation	✓		Driver Profile/ Memory System	✓	
Dashboard / Control Panel	✓		Paddle Shifters	✓	
Safety Belts	✓		Airbags	✓	
Central Locking System	✓		Remote Boot Release	✓	
Push Start Button System	✓		Fuel Cap Release	✓	
Luggage Compartment Light	✓		Luggage Compartment Trim & Cargo Net	✓	
Luggage Board	✓				

Underbody And Under The Hood

Items	Status	Comments		Status	Comments
Brake Fluid			Transmission Fluid		
Transmission Fluid Leaks			Power Steering Fluid		
Windshield Washer Fluids			Engine Oil		
Engine Oil Leaks		engine oil leak at timing cover and flywheel oil seal	Coolant Tank		
Coolant		top hose housing leak	Radiator		
Wiring			Engine Cover		
Battery			Exhaust System		
Power Steering Pump			Rack And Pinion, Linkage & Boots		
Tie Rods & Idler Arm			Control Arms & Ball Joints		front lower arm bushing torn
Sway Bars, Links & Bushings			Front Tyre (Left)		
Front Tyre (Right)			Rear Tyre (Left)		tyer worn out
Rear Tyre (Right)		tyer worn out			

Other information

Items	Notes		Notes

Inspection Summary

1) Carro Care Inspection and/or Report, shall not be taken as a guarantee that the vehicle will remain in the same condition, as various factors and incidents later could contribute the deterioration/change on vehicle condition. 2) Inspection of vehicle condition includes, using of computerized diagnostic equipment strictly for measuring and checking of faultcodes, visual checks and road test. 3) Carro Care will only conduct road test no more than 60kph at a short distance. Any intermittent abnormalities such as noise, jerky, vibrations etc may not be able to detect / identify.