













Car Make:	PERODUA	Engine Capacity:	1500
Car Model:	ALZA	Mileage:	77919km
Colour:	Blue Metallic	No. Of Seat:	7
Transmission:	automatic	No. Of Previous Owner:	1

Inspection Checklist

Inspector: MUHAMMAD FIKRI BIN NAZRI

 132 Pass	 0 Rectified	 0 To Be Rectified	N/A 32 Not Applicable
--	---	---	-----------------------

Road Test Checks

Items	Status	Comments		Status	Comments
Engine Starts Properly			Engine Noise		
Engine Idles Properly			Engine Acceleration		
Belting			Engine & Transmission Mounting		
Brake Pad Thickness			Brake Pedal		
Brake Lines, Hoses & Fittings			Suspension and Shock absorber		
Steering Operation			Undercarriage Noises		
Gear Box			Clutch Operates Properly	N/A	
Gauges Operate properly	N/A		Transmission / Transaxle Shift	N/A	
Tranmission/ Transaxle Noise	N/A		4X4 Operation	N/A	
Drive Axle / Transfer Case Noise	N/A		No Major Accident	N/A	
No Fire Damage	N/A		No Flood Damage	N/A	

Exterior

Exterior Images



Items	Status	Comments		Status	Comments
Front Fender (Left)	✓		Front Doors (Left)	✓	
Front Door Panel (Left)	✓		Left Side Mirror	✓	
Front Window (Left)	✓		Side Skirt (Left)	✓	
Rear Doors (Left)	✓		Rear Door Panel (Left)	✓	
Rear Window (Left)	✓		Rear Quarter Window (Left)	✓	
Rear Fender / Quarterpanel (Left)	✓		Rear End Exterior Lights (Left) - Reverse, Taillamp, Stop	✓	
Rear Windscreen	✓		Rear Bonnet	✓	
Rear Bumper	✓		Rear End Exterior Lights (Right) - Reverse, Taillamp, Stop	✓	
Rear Doors (Right)	✓		Rear Door Panel (Right)	✓	
Rear Window (Right)	✓		Rear Quarter Window (Right)	✓	
Rear Fender / Quarterpanel (Right)	✓		Side Skirt (Right)	✓	
Front Doors (Right)	✓		Front Door Panel (Right)	✓	
Front Fender (Right)	✓		Front Window (Right)	✓	
Right Side Mirror	✓		Front Bumper	✓	
Grille Inspection	✓		Front Bonnet, Support and Insulator	✓	
Front Bonnet Release	✓		Front Windscreen	✓	

Door Seals (All Doors)	✓		Door Handles	✓	
Body Panel Inspection	✓		Sunroof / Moonroof	N/A	
Convertible Top	N/A		Front End Exterior Lights (Right) - Headlight	✓	
Front End Exterior Lights (Left) - Headlight	✓		Side Exterior Lights	✓	
Hazard Lights	✓		Indicator Light	✓	
Fog Lamp Function	✓		Daytime Running Light	N/A	
Low / High Beam Function	✓		Auto On / Off Lights	N/A	
Rear Window Wiper Switch	✓		Windscreen Wipers Switch	✓	
Wiper Blades Front & Rear	✓		Power Window Controls	✓	
Outside Rear View Mirrors	✓		Sun Visors, Vanity Mirror & Light	✓	
Spare Tyre	✓		Jack & Tool Kit	✓	
Rims	✓		Wheel Alignment	✓	
Wheel Covers & Center Caps	✓				

Interior

Items	Status	Comments		Status	Comments
Radio / Cassette / CD / DVD Player	✓		Speakers	✓	
Alarm / Theft Deterrent System	✓		Reverse Camera	N/A	
Antenna	✓		Air Conditioning Switch Panel	✓	
Air Conditioning Parts	✓		Air Conditioning System	✓	
Front Aircon Vents	✓		Rear Aircon Vents	N/A	

Anti - Fog / Defroster Coil Damage	✓		Center Armrest / Console	✓	
Floor Mats	✓		Interior Carpet	✓	
Front Door Trim Board (Right)	✓		Front Door Trim Board (Left)	✓	
Door Trim Board 2nd Row (Right)	✓		Door Trim Board 2nd Row (Left)	✓	
A - Pillar Door Trim Board (Right)	✓		A - Pillar Door Trim Board (Left)	✓	
B - Pillar Door Trim Board (Right)	✓		B - Pillar Door Trim Board (Left)	✓	
C - Pillar Door Trim Board (Right)	✓		C - Pillar Door Trim Board (Left)	✓	
Glove Box	✓		Dashboard Drawer	✓	
Front Seat Including Electric Seat	N/A		Rear Seat Including Electric Seat	N/A	
Folding Seats	✓		Hot / Warmed Seats	N/A	
Cooled Seats	N/A		Seat & Head Restraint Adjustment	✓	
Headlining	✓		Parcel Shelf / Speaker Board / Tonneau Cover	✓	
Clock	✓		Power Outlet - 12 V Port / Cigarette Lighter	✓	
Power Outlet - USB Port / Cigarette Lighter	✓		Power Steering	✓	
Steering Wheel Controls	✓		Steering Wheel Condition	✓	
Tilt / Telescopic Steering Wheel	✓		Tripmeter And Odometer	✓	
Interior Courtesy, Dome & Map Lights	✓		Ashtrays	N/A	
Handbrake / Footbrake Lever	✓		Gear Knob	✓	
Horn	✓		Warning Light	✓	
Cruise Control Operation	N/A		Driver Profile/ Memory System	N/A	

Dashboard / Control Panel			Paddle Shifters	N/A	
Safety Belts			Airbags		
Central Locking System	N/A		Remote Boot Release		
Push Start Button System	N/A		Fuel Cap Release		
Luggage Compartment Light			Luggage Compartment Trim & Cargo Net		
Luggage Board					

Underbody And Under The Hood

Items	Status	Comments		Status	Comments
Brake Fluid			Transmission Fluid		
Transmission Fluid Leaks			Power Steering Fluid		
Windshield Washer Fluids			Engine Oil		
Engine Oil Leaks			Coolant Tank		
Coolant			Radiator		
Wiring			Engine Cover		
Battery			Exhaust System	N/A	
Power Steering Pump	N/A		Rack And Pinion, Linkage & Boots	N/A	
Tie Rods & Idler Arm	N/A		Control Arms & Ball Joints	N/A	
Sway Bars, Links & Bushings	N/A		Front Tyre (Left)		
Front Tyre (Right)			Rear Tyre (Left)		
Rear Tyre (Right)					

Other information

Items	Notes		Notes
Inspection Place	In House	Location	RX-2 Puchong South
E-Hailing	No	B2/B5 Forms	No
Remark			