

Plate No. (Sell with/Sell without).	Sell With	Brand	TOYOTA
Model	VOXY	Sub Model	4X2 BENSIN
Color	Hitam	Manufactured Year	2018
Transmission	Automatic	Fuel type	Petrol
Registration Card	Old	Registration Type	Private
Registration Date	2022-08-02	Engine Capacity	2000
Mileage	59507	Seat Number	7
No. of previous Owner	2	Service Book/Sticker	Yes
No. of Keys	2		

CARRO Certified



160-Point Inspection



5-Day Money Back Guarantee



12-Month Warranty for Engine & Gearbox






No Mileage Tampering











No Major Accidents, Fire & Flood Damage

Inspection Checklist

Inspector: INVT - Kholis Supriyanto

 149 Pass	 0 Rectified	 0 To Be Rectified	N/A 14 Not Applicable
--	---	---	-----------------------

Road Test Checks

Items	Status	Comments	Status	Comments
Engine Starts Properly Engine starts within 1 to 3 seconds upon cranking			Engine Noise No unusual noise when engine is in operation.	
Engine Idles Properly Engine idling stable between 650-980rpm			Engine Acceleration RPM synchronised with accelerator pedal	
Belting Hear out for belting noise & no visual cracks on belting			Engine & Transmission Mounting Test for any abnormal vibration when gear engage to D or R	
Brake Pad Thickness Brake pad is thicker than 4mm			Brake Pedal Test if brake pedal is loose or pedal is too low	

Brake Lines, Hoses & Fittings No visible leakage throughout the piping system	✓		Suspension and Shock absorber Visual check condition if there's any leak or test for any abnormal noise	✓	
Steering Operation Check for any noise from steering when operating	✓		Undercarriage Noises No unusual knocking sounds when going over humps or uneven roads	✓	
Gear Box Check gear up & down shift. Check for gear delay, jerk & slip.	✓		Clutch Operates Properly Clutch slip not detected during road test	N/A	
Gauges Operate properly Instrument panel gauges operates properly	✓		Transmission / Transaxle Shift same	✓	
Tranmission/ Transaxle Noise No abnormal sound during engaging transmission or transaxle system	✓		4X4 Operation Able to engage when activated	N/A	
Drive Axle / Transfer Case Noise Able to engage without an unusual sound when activated	N/A		No Major Accident No signs of impact or repairs to the chassis of the vehicle	✓	
No Fire Damage No visible or detectable signs of fire damage	✓		No Flood Damage No visible or detectable signs of flooding	✓	

Exterior

Items	Status	Comments		Status	Comments
Door Seals (All Doors) Rubber seals are not torn	✓		Door Handles Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓	
Front Bumper Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓		Front Fender (Left) Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓	
Front Doors (Right) Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓		Front Door Panel (Right) Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓	
Front Doors (Left) Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓		Front Door Panel (Left) Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓	
Front Bonnet, Support and Insulator Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓		Front Fender (Right) Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓	
Rear Bonnet Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓		Rear Fender / Quarterpanel (Right) Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓	
Rear Fender / Quarterpanel (Left) Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓		Rear Bumper Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓	

Rear Doors (Right) Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓	Rear Door Panel (Right) Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓
Rear Doors (Left) Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓	Rear Door Panel (Left) Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓
Side Skirt (Left) Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓	Side Skirt (Right) Less than 5 dents deeper than 5 mm and less than 5 scratches longer than 5 cm	✓
Body Panel Inspection No signs of corrosion or paint cracks	✓	Grille Inspection No visible cracks	✓
Sunroof / Moonroof Sunroof: Able to open and close without any signs of water seepage. Moonroof: No water seepage present	✓	Convertible Top Able to open and close upon activation with no visible leaks when fully sealed	N/A
Front Bonnet Release Able to unlock bonnet & cable not loose or lever not crack	✓	Front Windscreen Check front windscreen condition from chip or crack	✓
Rear Windscreen Check rear windscreen condition from chip or crack	✓	Front Window (Left) Check front left window condition from chip or crack	✓
Front Window (Right) Check front right window condition from chip or crack	✓	Rear Window (Right) Check rear right window condition from chip or crack	✓
Rear Window (Left) Check rear left window condition from chip or crack	✓	Rear Quarter Window (Left) Check rear left quarter window condition from chip or crack	✓
Rear Quarter Window (Right) Check rear right quarter window condition from chip or crack	✓	Rear Window Wiper Switch Wipers are functional when switch is activated	✓
Windscreen Wipers Switch Wipers are functional when switch is activated	✓	Wiper Blades Front & Rear Wipers are wiping clear	✓
Power Window Controls Controls are functional upon activation	✓	Left Side Mirror No cracks on the mirrors and are adjustable when activated	✓
Right Side Mirror No cracks on the mirrors and are adjustable when activated	✓	Outside Rear View Mirrors No cracks on the mirrors and are adjustable when activated	✓
Sun Visors, Vanity Mirror & Light Visors are able to hold its position when left untouched. No visible cracks on vanity mirrors. Lights are working when activated	✓	Front End Exterior Lights (Left) - Headlight Lights are functional when activated	✓
Front End Exterior Lights (Right) - Headlight Lights are functional when activated	✓	Side Exterior Lights Lights are functional when activated	N/A
Rear End Exterior Lights (Left) - Reverse, Taillamp, Stop Lights are functional when activated	✓	Rear End Exterior Lights (Right) - Reverse, Taillamp, Stop Lights are functional when activated	✓

Hazard Lights Lights are functional when activated	✓		Indicator Light Lights are functional when activated	✓	
Fog Lamp Function Lights are functional when activated	✓		Daytime Running Light Lights are functional when activated	N/A	
Low / High Beam Function Lights are functional when activated	✓		Auto On / Off Lights Lights are functional when activated	✓	
Spare Tyre Check spare tyre condition	✓		Jack & Tool Kit Check tools set are complete & functional	✓	
Rims No dents or cracks on the rims. Scratches may be present	✓		Wheel Alignment Car will move straight when steering wheel is fixed in a straight position	✓	
Wheel Covers & Center Caps Center cap will be present. Not applicable if vehicle's doesn't have center caps	✓				

Interior

Items	Status	Comments		Status	Comments
Radio / Cassette / CD / DVD Player Buttons and Touch Screen are functional when pressed. Does not include remote controls	✓		Speakers Able to produce sound when activated	✓	
Alarm / Theft Deterrent System Alarms are functional when activated	✓		Reverse Camera Reverse camera able to display image upon activation	✓	
Antenna Can receive radio static	✓		Air Conditioning Switch Panel Buttons are operational when activated. Button cosmetics are as-per-condition	✓	
Air Conditioning Parts Parts are operational when activated	✓		Air Conditioning System System is able to produce cold air	✓	
Front Aircon Vents Air con vents are able to operate when activated. No visible cracks on the vent	✓		Rear Aircon Vents Air con vents are able to operate when activated. No visible cracks on the vent	✓	
Anti - Fog / Defroster Coil Damage Heating element is functional when activated	✓		Center Armrest / Console Scratches no longer than 5cm and leather is not torn. Discoloring may be present	✓	
Floor Mats Check floor mats condition for any wear or torn	✓		Interior Carpet Check interior floor carpet condition for torn, wear or wet	✓	
Front Door Trim Board (Right) No visible cracks or scratches longer than 5cm	✓		Front Door Trim Board (Left) No visible cracks or scratches longer than 5cm	✓	
Door Trim Board 2nd Row (Right) No visible cracks or scratches longer than 5cm	✓		Door Trim Board 2nd Row (Left) No visible cracks or scratches longer than 5cm	✓	

A – Pillar Door Trim Board (Right) No visible cracks or scratches longer than 5cm			A – Pillar Door Trim Board (Left) No visible cracks or scratches longer than 5cm		
B – Pillar Door Trim Board (Right) No visible cracks or scratches longer than 5cm			B – Pillar Door Trim Board (Left) No visible cracks or scratches longer than 5cm		
C – Pillar Door Trim Board (Right) No visible cracks or scratches longer than 5cm			C – Pillar Door Trim Board (Left) No visible cracks or scratches longer than 5cm		
Glove Box Able to open and close securely when engaged			Dashboard Drawer Able to open and close with no visible cracks and scratches longer than 5cm		
Front Seat Including Electric Seat Seats are able to be adjusted when engaged. Sounds may be present during operation			Rear Seat Including Electric Seat Seats can be adjusted when activated		
Folding Seats Seat(s) can be secured in a folded position			Hot / Warmed Seats Temperature changes when activated	N/A	
Cooled Seats Temperature changes when activated	N/A		Seat & Head Restraint Adjustment Adjustments are functional		
Headlining No signs of sinkages			Parcel Shelf / Speaker Board / Tonneau Cover Check condition for wear, torn or missing		
Clock Able to display the current time			Power Outlet - 12 V Port / Cigarette Lighter Able to function when activated		
Power Outlet - USB Port / Cigarette Lighter Able to function when activated			Power Steering Steering wheel can engage full lock range motion with mechanical assistance		
Steering Wheel Controls Buttons are functional when activated			Steering Wheel Condition Steering wheel does not have leather peeling		
Tilt / Telescopic Steering Wheel Able to be adjusted when activated			Tripmeter And Odometer Tripmeter can be resetted. Odometer clocks mileage.		
Interior Courtesy, Dome & Map Lights Parts are functional when activated			Ashtrays Check open/close ashtray function & condition	N/A	
Handbrake / Footbrake Lever Parts are functional when activated			Gear Knob Able to remain in a locked position when gears are activated		
Horn Able to produce warning sounds when activated			Warning Light When ignition is activated, indicator lights are present		
Cruise Control Operation Feature is functional when activated			Driver Profile/ Memory System Memory system is functional when activated		
Dashboard / Control Panel No visible peeling and cracks more than 5cm			Paddle Shifters Able to function when activated	N/A	

Safety Belts Safety belt engages in lock position when force is applied	✓		Airbags Airbag warning lights not present on vehicle dashboard	✓	
Central Locking System All Locks are secured upon activation	✓		Remote Boot Release Boot opens and closes upon activation	N/A	
Push Start Button System Engine starts and stops when button is pressed	✓		Fuel Cap Release Cap opens and closes securely	✓	
Luggage Compartment Light Lights are functional	✓		Luggage Compartment Trim & Cargo Net Available when provided by the previous owner	N/A	
Luggage Board Must be available.If missing must install.	✓				

Underbody And Under The Hood

Items	Status	Comments	Items	Status	Comments
Brake Fluid Fluids are filled to specified levels	✓		Transmission Fluid Fluids are filled to specified levels	✓	
Transmission Fluid Leaks No visible oil droplets	✓		Power Steering Fluid Fluids are filled to specified levels	N/A	
Windshield Washer Fluids Fluids are filled to specified levels	✓		Engine Oil Must be replaced with new oil plus oil filter.	✓	
Engine Oil Leaks No visible oil droplets	✓		Coolant Tank No cracks and leakages	✓	
Coolant Coolant is filled to specified levels	✓		Radiator No visible leakages	✓	
Wiring No visible damages or burnt ends	✓		Engine Cover Not torn and able to cover engine securely	✓	
Battery Voltage above 12.25 V and battery is less than 1.5 years old	✓		Exhaust System Condition must be normal without loud noise	✓	
Power Steering Pump Able to assist other power steering components to function properly and no visible oil leakages	N/A		Rack And Pinion, Linkage & Boots No knocking noise when going over a hump or uneven road	✓	
Tie Rods & Idler Arm No knocking noise when going over a hump or uneven road	✓		Control Arms & Ball Joints No knocking noise when going over a hump or uneven road	✓	
Sway Bars, Links & Bushings No knocking noise when going over a hump or uneven road	✓		Front Tyre (Left) Tyre wear must not be less than 3mm and lifespan must not more than 6 years	✓	
Front Tyre (Right) Tyre wear must not be less than 3mm and lifespan must not more than 6 years	✓		Rear Tyre (Left) Tyre wear must not be less than 3mm and lifespan must not more than 6 years	✓	

Rear Tyre (Right)

Tyre wear must not be less than 3mm and lifespan must not more than 6 years

**Other information**

Items	Notes		Notes
Foto mobil tambahan		Foto kerusakan Tambahan	
Inspection Place	in house	Location	115
Resiko	low	Remark	
Inspection Summary	Secara keseluruhan kondisi unit baik		