



Plate No. (Sell with/Sell without).	Sell Without	Brand	BMW
Model	330LI	Sub Model	M SPORT
Color	N/A	Manufactured Year	2021
Transmission	Automatic	Fuel type	Petrol
Registration Card	New	Registration Type	Private
Registration Date	2021-07-30	Engine Capacity	2000
Mileage	53451	Seat Number	5
No. of previous Owner	1	Service Book/Sticker	No
No. of Keys	2		


CARRO Certified




160-Point Inspection




5-Day Money Back Guarantee



12-Month Warranty for Engine & Gearbox






No Mileage Tampering













No Major Accidents, Fire & Flood Damage

Inspection Checklist

Inspector: Nur Syazwani Binti Hamzah

 152 Pass	 0 Rectified	 0 To Be Rectified	N/A 12 Not Applicable
--	---	---	-----------------------

Road Test Checks

Items	Status	Comments	Status	Comments
Engine Starts Properly				Engine Noise
Engine Idles Properly				Engine Acceleration
Belting				Engine & Transmission Mounting
Brake Pad Thickness				Brake Pedal
Brake Lines, Hoses & Fittings				Suspension and Shock absorber

Steering Operation	✓		Undercarriage Noises	✓	
Gear Box	✓		Clutch Operates Properly	N/A	
Gauges Operate properly	✓		Transmission / Transaxle Shift	✓	
Tranmission/ Transaxle Noise	✓		4X4 Operation	N/A	
Drive Axle / Transfer Case Noise	✓		No Major Accident	✓	
No Fire Damage	✓		No Flood Damage	✓	

Exterior

Items	Status	Comments		Status	Comments
Door Seals (All Doors)	✓		Door Handles	✓	
Front Bumper	✓		Front Fender (Left)	✓	
Front Doors (Right)	✓		Front Door Panel (Right)	✓	
Front Doors (Left)	✓		Front Door Panel (Left)	✓	
Front Bonnet, Support and Insulator	✓		Front Fender (Right)	✓	
Rear Bonnet	✓		Rear Fender / Quarterpanel (Right)	✓	
Rear Fender / Quarterpanel (Left)	✓		Rear Bumper	✓	
Rear Doors (Right)	✓		Rear Door Panel (Right)	✓	
Rear Doors (Left)	✓		Rear Door Panel (Left)	✓	
Side Skirt (Left)	✓		Side Skirt (Right)	✓	
Body Panel Inspection	✓		Grille Inspection	✓	
Sunroof / Moonroof	✓		Convertible Top	N/A	

Front Bonnet Release	✓		Front Windscreen	✓	
Rear Windscreen	✓		Front Window (Left)	✓	
Front Window (Right)	✓		Rear Window (Right)	✓	
Rear Window (Left)	✓		Rear Quarter Window (Left)	✓	
Rear Quarter Window (Right)	✓		Rear Window Wiper Switch	N/A	
Windscreen Wipers Switch	✓		Wiper Blades Front & Rear	✓	
Power Window Controls	✓		Left Side Mirror	✓	
Right Side Mirror	✓		Outside Rear View Mirrors	N/A	
Sun Visors, Vanity Mirror & Light	✓		Front End Exterior Lights (Left) - Headlight	✓	
Front End Exterior Lights (Right) - Headlight	✓		Side Exterior Lights	✓	
Rear End Exterior Lights (Left) - Reverse, Taillamp, Stop	✓		Rear End Exterior Lights (Right) - Reverse, Taillamp, Stop	✓	
Hazard Lights	✓		Indicator Light	✓	
Fog Lamp Function	✓		Daytime Running Light	✓	
Low / High Beam Function	✓		Auto On / Off Lights	✓	
Spare Tyre	N/A		Jack & Tool Kit	N/A	
Rims	✓		Wheel Alignment	✓	
Wheel Covers & Center Caps	✓				

Interior

Items	Status	Comments	Status	Comments
Radio / Cassette / CD / DVD Player	✓		Speakers	✓

Alarm / Theft Deterrent System	✓		Reverse Camera	✓	
Antenna	✓		Air Conditioning Switch Panel	✓	
Air Conditioning Parts	✓		Air Conditioning System	✓	
Front Aircon Vents	✓		Rear Aircon Vents	✓	
Anti - Fog / Defroster Coil Damage	✓		Center Armrest / Console	✓	
Floor Mats	✓		Interior Carpet	✓	
Front Door Trim Board (Right)	✓		Front Door Trim Board (Left)	✓	
Door Trim Board 2nd Row (Right)	✓		Door Trim Board 2nd Row (Left)	✓	
A - Pillar Door Trim Board (Right)	✓		A - Pillar Door Trim Board (Left)	✓	
B - Pillar Door Trim Board (Right)	✓		B - Pillar Door Trim Board (Left)	✓	
C - Pillar Door Trim Board (Right)	✓		C - Pillar Door Trim Board (Left)	✓	
Glove Box	✓		Dashboard Drawer	✓	
Front Seat Including Electric Seat	✓		Rear Seat Including Electric Seat	✓	
Folding Seats	✓		Hot / Warmed Seats	N/A	
Cooled Seats	N/A		Seat & Head Restraint Adjustment	✓	
Headlining	✓		Parcel Shelf / Speaker Board / Tonneau Cover	✓	
Clock	✓		Power Outlet - 12 V Port / Cigarette Lighter	✓	
Power Outlet - USB Port / Cigarette Lighter	✓		Power Steering	✓	
Steering Wheel Controls	✓		Steering Wheel Condition	✓	
Tilt / Telescopic Steering Wheel	✓		Tripmeter And Odometer	✓	

Interior Courtesy, Dome & Map Lights	✓		Ashtrays	✓	
Handbrake / Footbrake Lever	✓		Gear Knob	✓	
Horn	✓		Warning Light	✓	
Cruise Control Operation	✓		Driver Profile/ Memory System	✓	
Dashboard / Control Panel	✓		Paddle Shifters	✓	
Safety Belts	✓		Airbags	✓	
Central Locking System	✓		Remote Boot Release	✓	
Push Start Button System	✓		Fuel Cap Release	✓	
Luggage Compartment Light	✓		Luggage Compartment Trim & Cargo Net	✓	
Luggage Board	✓				

Underbody And Under The Hood

Items	Status	Comments		Status	Comments
Brake Fluid	✓		Transmission Fluid	✓	
Transmission Fluid Leaks	✓		Power Steering Fluid	N/A	
Windshield Washer Fluids	✓		Engine Oil	✓	
Engine Oil Leaks	✓		Coolant Tank	✓	
Coolant	✓		Radiator	✓	
Wiring	✓		Engine Cover	✓	
Battery	✓		Exhaust System	✓	
Power Steering Pump	N/A		Rack And Pinion, Linkage & Boots	✓	

Tie Rods & Idler Arm			Control Arms & Ball Joints		
Sway Bars, Links & Bushings			Front Tyre (Left)		
Front Tyre (Right)			Rear Tyre (Left)		
Rear Tyre (Right)					

Other information

Items	Notes		Notes
Inspection Place	In House	Location	myTukar [Body & Paint] - Ulu Tiram
E-Hailing	No	B2/B5 Forms	No
Remark	N/A	Inspection Summary	<p>#CARRO DOES NOT GUARANTEE THE AUTHENTICITY OF MILEAGE SHOWN DURING INSPECTION</p> <p>#CARRO DOES NOT GUARANTEE ON THE VALIDITY OF NEW CAR WARRANTY</p> <p>#THE STATUS OF THE CAR AS OF DATE OF INSPECTION AND DOES NOT GUARANTEE THE QUALITY OF CAR ONWARDS</p> <p>#BIDDER HAVE TO DO PAYMENT 30% FIRST THEN ONLY WILL PROCEED TRANSACTION WITH SELLER</p> <p>#CAR NO UNDERCARRIAGE INSPECTION DUE TO NO FACILITIES</p> <p>#ENGINE NUMBER CANNOT IDENTIFY OR SEEN</p> <p>#CORPORATE CAR , SURRENDER OF THE VEHICLE MAY TAKE UP TO 14 DAYS</p> <p>#E-HAILING CAR , SURRENDER OF VEHICLE MAY TAKE UP TO 14DAYS</p> <p>#ROADTEST AT SHORT DISTANCE UNDER 50KM/H. ANY FAULTY AT HIGH GEAR OR HIGH RPM CANNOT BE IDENTIFY</p> <p>#AP FORM 1,8 AND 69 PROVIDED - (EXAMPLE - AP SYKT WANA MOTOR) #AP NOT PROVIDED</p>