

#### 160-Point Inspection Checklist

TOYOTA C-HR H	/BRID	Inspector:	Sethu Narayanan
1.8S CVT	<u>View Car</u>	Date of Inspection:	12th March 2025
Plate No. (Sell with/Sell without).	Sell With	Brand	ΤΟΥΟΤΑ
Model	C-HR HYBRID 1.8S CVT	Sub Model	-
Color	Yellow	Manufactured Year	2017
Transmission	Automatic	Fuel type	Petrol Electric
Registration Card	New	<b>Registration Type</b>	Company
Registration Date	2018-04-26	<b>Engine Capacity</b>	1797
Mileage	40484	Seat Number	5
No. of previous Owner	1	Service Book/Sticker	Yes
No. of Keys	1		



#### **Road Test Checks**

Items	Status	Comments		Status	Comments
Engine Starts Properly	Ø		Engine Noise	<b>v</b>	
Engine Idles Properly	Ø		Engine Acceleration	<b>O</b>	

Belting	N/A	Engine & Transmission Mounting
Brake Pad Thickness	•	Brake Pedal
Brake Lines, Hoses & Fittings	•	Suspension and Shock obsorber
Steering Operation	•	Undercarriage Noises
Gear Box	•	Clutch Operates Properly N/A
Gauges Operate properly	•	Transmission / Transaxle
Tranmission/ Transaxle Noise	N/A	4X4 Operation N/A
Drive Axle / Transfer Case Noise	N/A	No Major Accident
No Fire Damage	•	No Flood Damage

### Exterior

Items	Status	Comments		Status	Comments
Door Seals (All Doors)	<b>S</b>		Door Handles	Ø	
Front Bumper	Ø		Front Fender (Left)	<b>O</b>	
Front Doors (Right)	Ø		Front Door Panel (Right)	Ø	
Front Doors (Left)	Ø		Front Door Panel (Left)	Ø	
Front Bonnet, Support and Insulator	Ø		Front Fender (Right)	Ø	
Rear Bonnet	Ø		Rear Fender / Quarterpanel (Right)	Ø	
Rear Fender / Quarterpanel (Left)	Ø		Rear Bumper	<b>I</b>	
Rear Doors (Right)	Ø		Rear Door Panel (Right)	Ø	
Rear Doors (Left)	<b>v</b>		Rear Door Panel (Left)	<b>O</b>	

Side Skirt (Left)	•	Side Skirt (Right)	<b>v</b>	
Body Panel Inspection	<b>I</b>	Grille Inspection	<ul> <li>Image: A start of the start of</li></ul>	
Sunroof / Moonroof	N/A	Convertible Top	N/A	
Front Bonnet Release	0	Front Windscreen	<b></b>	
Rear Windscreen	0	Front Window (Left)	<b>I</b>	
Front Window (Right)	<b>Ø</b>	Rear Window (Right)	<b>v</b>	
Rear Window (Left)	0	Rear Quarter Window (Left)	<b>I</b>	
Rear Quarter Window (Right)	0	Rear Window Wiper Switch	<b></b>	
Windscreen Wipers Switch	0	Wiper Blades Front & Rear	<b></b>	
Power Window Controls	0	Left Side Mirror	<b></b>	
Right Side Mirror	<b>Ø</b>	Outside Rear View Mirrors	<b>v</b>	
Sun Visors, Vanity Mirror & Light	0	Front End Exterior Lights (Left) - Headlight	<b>v</b>	
Front End Exterior Lights (Right) - Headlight	<b>I</b>	Side Exterior Lights	<ul> <li>Image: A start of the start of</li></ul>	
Rear End Exterior Lights (Left) - Reverse, Taillamp, Stop	0	Rear End Exterior Lights (Right) - Reverse, Taillamp, Stop	<b>I</b>	
Hazard Lights	0	Indicator Light	<b>I</b>	
Fog Lamp Function	N/A	Daytime Running Light	<b>I</b>	
Low / High Beam Function	0	Auto On / Off Lights	<b></b>	
Spare Tyre	N/A	Jack & Tool Kit	<b>v</b>	
Rims	<b>Ø</b>	Wheel Alignment	<b>v</b>	
Wheel Covers & Center Caps	0			

# Interior

Items	Status	Comments		Status	Comments
Radio / Cassette / CD / DVD Player	Ø		Speakers	Ø	
Alarm / Theft Deterrent System	Ø		Reverse Camera	Ø	
Antenna	Ø		Air Conditioning Switch Panel	Ø	
Air Conditioning Parts	Ø		Air Conditioning System	<b>v</b>	
Front Aircon Vents	Ø		Rear Aircon Vents	N/A	
Anti - Fog / Defroster Coil Damage	<b>v</b>		Center Armrest / Console	<b>S</b>	
Floor Mats	Ø		Interior Carpet	<b>I</b>	
Front Door Trim Board (Right)	Ø		Front Door Trim Board (Left)	<b>S</b>	
Door Trim Board 2nd Row (Right)	Ø		Door Trim Board 2nd Row (Left)	<b>v</b>	
A - Pillar Door Trim Board (Right)	Ø		A - Pillar Door Trim Board (Left)	<b>I</b>	
B - Pillar Door Trim Board (Right)	Ø		B - Pillar Door Trim Board (Left)	<b>I</b>	
C - Pillar Door Trim Board (Right)	Ø		C - Pillar Door Trim Board (Left)	<b>I</b>	
Glove Box	Ø		Dashboard Drawer	N/A	
Front Seat Including Electric Seat	N/A		Rear Seat Including Electric Seat	N/A	
Folding Seats	Ø		Hot / Warmed Seats	N/A	
Cooled Seats	N/A		Seat & Head Restraint Adjustment	<b>v</b>	
Headlining	Ø		Parcel Shelf / Speaker Board / Tonneau Cover	Ø	
Clock	Ø		Power Outlet - 12 V Port / Cigarette Lighter	Ø	

Power Outlet - USB Port / Cigarette Lighter		Power Steering	
Steering Wheel Controls	•	Steering Wheel Condition	
Tilt / Telescopic Steering Wheel		Tripmeter And Odometer	<b>O</b>
Interior Courtesy, Dome & Map Lights		Ashtrays	N/A
Handbrake / Footbrake Lever		Gear Knob	
Horn		Warning Light	
Cruise Control Operation		Driver Profile/ Memory System	N/A
Dashboard / Control Panel		Paddle Shifters	N/A
Safety Belts		Airbags	
Central Locking System		Remote Boot Release	
Push Start Button System		Fuel Cap Release	
Luggage Compartment Light		Luggage Compartment Trim & Cargo Net	
Luggage Board	<b>•</b>		

## **Underbody And Under The Hood**

Items	Status	Comments		Status	Comments
Brake Fluid	Ø		Transmission Fluid	<b>v</b>	
Transmission Fluid Leaks	Ø		Power Steering Fluid	N/A	
Windshield Washer Fluids	Ø		Engine Oil	<b>v</b>	
Engine Oil Leaks	Ø		Coolant Tank	<b>v</b>	
Coolant	Ø		Radiator	<b>v</b>	

Wiring	•	Engine Cover	<b>I</b>
Battery	•	Exhaust System	<b>I</b>
Power Steering Pump	N/A	Rack And Pinion, Linkage & Boots	<b>O</b>
Tie Rods & Idler Arm	•	Control Arms & Ball Joints	<b>O</b>
Sway Bars, Links & Bushings	•	Front Tyre (Left)	<b>O</b>
Front Tyre (Right)	•	Rear Tyre (Left)	<b>O</b>
Rear Tyre (Right)	<b>I</b>		

#### Other information

Items	Notes	Notes
Inspection Summary	1) Carro Care Inspection and/or Report, shall not be taken as a guarantee that the vehicle will remain in the same condition, as various factors and incidents later could contribute the deterioration/change on vehicle condition. 2) Inspection of vehicle condition includes, using of computerized diagnostic equipment strictly for measuring and checking of faultcodes, visual checks and road test. 3) Carro Care will only conduct road test no more than 60kph at a short distance. Any intermittent abnormalities such as noise, jerky, vibrations etc may not be able to detect / identify.	