



Plate No. (Sell with/Sell without).	Sell With	Brand	Toyota
Model	YARIS	Sub Model	-
Color	White	Manufactured Year	2022
Base Color	20	Transmission	Automatic
Color Variation	N/A	Fuel type	petrol
Registration Card	Old	Registration Type	company
Registration Date	2022-07-01	Engine No.	3NR5583875
Chassis No.	MR2KC3F3X01432732	Engine Capacity	1200
Mileage	33958	Seat Number	5
No. of previous Owner	N/A	Service Book/Sticker	Yes
AP	N/A	No. of Keys	2


CARRO Certified




160-Point Inspection




5-Day Money Back Guarantee



12-Month Warranty for Engine & Gearbox






No Mileage Tampering













No Major Accidents, Fire & Flood Damage

Inspection Checklist

Inspector: Sakkarapol Chulapita - TH Record Mgr.

 152 Pass	 0 Rectified	 0 To Be Rectified	N/A 12 Not Applicable
--	---	---	-----------------------

Road Test Checks

Items	Status	Comments	Status	Comments
Engine Starts Properly			Engine Noise	
Engine Idles Properly			Engine Acceleration	
Belting			Engine & Transmission Mounting	
Brake Pad Thickness			Brake Pedal	
Brake Lines, Hoses & Fittings			Suspension and Shock absorber	

Steering Operation	✓		Undercarriage Noises	✓	
Gear Box	✓		Clutch Operates Properly	✓	
Gauges Operate properly	✓		Transmission / Transaxle Shift	✓	
Tranmission/ Transaxle Noise	✓		4X4 Operation	N/A	
Drive Axle / Transfer Case Noise	✓		No Major Accident	✓	
No Fire Damage	✓		No Flood Damage	✓	

Exterior

Exterior Images



Items	Status	Comments	Status	Comments
Door Seals (All Doors)	✓		Door Handles	✓
Front Bumper	✓		Front Fender (Left)	✓
Front Doors (Right)	✓		Front Door Panel (Right)	✓
Front Doors (Left)	✓		Front Door Panel (Left)	✓
Front Bonnet, Support and Insulator	✓		Front Fender (Right)	✓
Rear Bonnet	✓		Rear Fender / Quarterpanel (Right)	✓

Rear Fender / Quarterpanel (Left)	✓		Rear Bumper	✓	
Rear Doors (Right)	✓		Rear Door Panel (Right)	✓	
Rear Doors (Left)	✓		Rear Door Panel (Left)	✓	
Side Skirt (Left)	✓		Side Skirt (Right)	✓	
Body Panel Inspection	✓		Grille Inspection	✓	
Sunroof / Moonroof	N/A		Convertible Top	N/A	
Front Bonnet Release	✓		Front Windscreen	✓	
Rear Windscreen	✓		Front Window (Left)	✓	
Front Window (Right)	✓		Rear Window (Right)	✓	
Rear Window (Left)	✓		Rear Quarter Window (Left)	✓	
Rear Quarter Window (Right)	✓		Rear Window Wiper Switch	✓	
Windscreen Wipers Switch	✓		Wiper Blades Front & Rear	✓	
Power Window Controls	✓		Left Side Mirror	✓	
Right Side Mirror	✓		Outside Rear View Mirrors	✓	
Sun Visors, Vanity Mirror & Light	✓		Front End Exterior Lights (Left) - Headlight	✓	
Front End Exterior Lights (Right) - Headlight	✓		Side Exterior Lights	✓	
Rear End Exterior Lights (Left) - Reverse, Taillamp, Stop	✓		Rear End Exterior Lights (Right) - Reverse, Taillamp, Stop	✓	
Hazard Lights	✓		Indicator Light	✓	
Fog Lamp Function	✓		Daytime Running Light	✓	
Low / High Beam Function	✓		Auto On / Off Lights	N/A	

Spare Tyre	✓		Jack & Tool Kit	✓	
Rims	✓		Wheel Alignment	✓	
Wheel Covers & Center Caps	✓				

Interior

Interior Images



Items	Status	Comments		Status	Comments
Radio / Cassette / CD / DVD Player	✓		Speakers	✓	
Alarm / Theft Deterrent System	✓		Reverse Camera	✓	
Antenna	✓		Air Conditioning Switch Panel	✓	
Air Conditioning Parts	✓		Air Conditioning System	✓	
Front Aircon Vents	✓		Rear Aircon Vents	N/A	
Anti - Fog / Defroster Coil Damage	✓		Center Armrest / Console	✓	
Floor Mats	✓		Interior Carpet	✓	
Front Door Trim Board (Right)	✓		Front Door Trim Board (Left)	✓	
Door Trim Board 2nd Row (Right)	✓		Door Trim Board 2nd Row (Left)	✓	
A - Pillar Door Trim Board (Right)	✓		A - Pillar Door Trim Board (Left)	✓	

B - Pillar Door Trim Board (Right)	✓		B - Pillar Door Trim Board (Left)	✓	
C - Pillar Door Trim Board (Right)	✓		C - Pillar Door Trim Board (Left)	✓	
Glove Box	✓		Dashboard Drawer	✓	
Front Seat Including Electric Seat	✓		Rear Seat Including Electric Seat	✓	
Folding Seats	✓		Hot / Warmed Seats	N/A	
Cooled Seats	N/A		Seat & Head Restraint Adjustment	✓	
Headlining	✓		Parcel Shelf / Speaker Board / Tonneau Cover	✓	
Clock	✓		Power Outlet - 12 V Port / Cigarette Lighter	✓	
Power Outlet - USB Port / Cigarette Lighter	✓		Power Steering	✓	
Steering Wheel Controls	✓		Steering Wheel Condition	✓	
Tilt / Telescopic Steering Wheel	✓		Tripmeter And Odometer	✓	
Interior Courtesy, Dome & Map Lights	✓		Ashtrays	✓	
Handbrake / Footbrake Lever	✓		Gear Knob	✓	
Horn	✓		Warning Light	✓	
Cruise Control Operation	N/A		Driver Profile/ Memory System	N/A	
Dashboard / Control Panel	✓		Paddle Shifters	N/A	
Safety Belts	✓		Airbags	✓	
Central Locking System	✓		Remote Boot Release	✓	
Push Start Button System	N/A		Fuel Cap Release	✓	
Luggage Compartment Light	✓		Luggage Compartment Trim & Cargo Net	✓	

Luggage Board



Underbody And Under The Hood

Items	Status	Comments		Status	Comments
Brake Fluid			Transmission Fluid		
Transmission Fluid Leaks			Power Steering Fluid		
Windshield Washer Fluids			Engine Oil		
Engine Oil Leaks			Coolant Tank		
Coolant			Radiator		
Wiring			Engine Cover		
Battery			Exhaust System		
Power Steering Pump			Rack And Pinion, Linkage & Boots		
Tie Rods & Idler Arm			Control Arms & Ball Joints		
Sway Bars, Links & Bushings			Front Tyre (Left)		
Front Tyre (Right)			Rear Tyre (Left)		
Rear Tyre (Right)					

Other information

Items	Notes		Notes
เกออดตัวถ้ง	a	เกออดภายใน	ai
Inspection Place	In House	Location	Carro Automall - King Keaw Road

Remark	N/A	Inspection Summary	<p>รถทุกคันของเราผ่านการตรวจสอบกว่า 160 จุด โดยผู้เชี่ยวชาญ โดยจะวิเคราะห์ทุกแง่มุมของรถ และบันทึกข้อบกพร่องที่รถอาจมีไม่ว่าจะเล็กน้อยแค่ไหนก็ตาม วิธีนี้ช่วยให้คุณได้ภาพที่ชัดเจนของสภาพรถที่คุณได้รับ และจะไม่ถูกมองข้ามหรือแปลกใจในระหว่างการดูหรือซื้อ หากมีข้อบกพร่องที่สำคัญใดๆ กับรถที่อาจส่งผลกระทบต่อประสิทธิภาพหรือความทนทาน เราจะแก้ไขให้ตรงจุดก่อนที่จะลงรายการรถเพื่อความอุ่นใจของคุณ โปรดดูรายงานโดยละเอียดของเราด้านล่างและแจ้งให้เราทราบหากคุณมีคำถามใดๆ</p>
--------	-----	--------------------	--