


BMW X3 SDRIVE 20I
MSPT ADAPTIVE HL LED FL [View Car](#)


Inspector: Sharvin Kumar A/L Nedunchelian
 Date of Inspection: 9th September 2025

Plate No. (Sell with/Sell without).	Sell With	Brand	BMW
Model	X3 SDRIVE 20I MSPT ADAPTIVE HL LED FL	Sub Model	x3
Color	Blue	Manufactured Year	2020
Transmission	Automatic	Fuel type	Petrol
Registration Card	New	Registration Type	Company
Registration Date	2020-10-22	Engine Capacity	1998
Mileage	123006	Seat Number	5
No. of previous Owner	1	Service Book/Sticker	Yes
No. of Keys	1		

CARRO Certified




160-Point Inspection




5-Day Money Back Guarantee



12-Month Warranty for Engine & Gearbox






No Mileage Tampering







No Major Accidents, Fire & Flood Damage

Inspection Checklist

Inspector: Sharvin Kumar A/L Nedunchelian

 149 Pass	 0 Rectified	 0 To Be Rectified	N/A 15 Not Applicable
--	---	---	-----------------------

Road Test Checks

Items	Status	Comments	Status	Comments
Engine Starts Properly			Engine Noise	
Engine Idles Properly			Engine Acceleration	

Belting	✓		Engine & Transmission Mounting	✓	
Brake Pad Thickness	✓		Brake Pedal	✓	
Brake Lines, Hoses & Fittings	✓		Suspension and Shock absorber	✓	
Steering Operation	✓		Undercarriage Noises	✓	
Gear Box	✓		Clutch Operates Properly	N/A	
Gauges Operate properly	✓		Transmission / Transaxle Shift	✓	
Tranmission/ Transaxle Noise	N/A		4X4 Operation	N/A	
Drive Axle / Transfer Case Noise	N/A		No Major Accident	✓	
No Fire Damage	✓		No Flood Damage	✓	

Exterior

Items	Status	Comments		Status	Comments
Door Seals (All Doors)	✓		Door Handles	✓	
Front Bumper	✓		Front Fender (Left)	✓	
Front Doors (Right)	✓		Front Door Panel (Right)	✓	
Front Doors (Left)	✓		Front Door Panel (Left)	✓	
Front Bonnet, Support and Insulator	✓		Front Fender (Right)	✓	
Rear Bonnet	✓		Rear Fender / Quarterpanel (Right)	✓	
Rear Fender / Quarterpanel (Left)	✓		Rear Bumper	✓	
Rear Doors (Right)	✓		Rear Door Panel (Right)	✓	
Rear Doors (Left)	✓		Rear Door Panel (Left)	✓	

Side Skirt (Left)	✓		Side Skirt (Right)	✓	
Body Panel Inspection	✓		Grille Inspection	✓	
Sunroof / Moonroof	N/A		Convertible Top	N/A	
Front Bonnet Release	✓		Front Windscreen	✓	
Rear Windscreen	✓		Front Window (Left)	✓	
Front Window (Right)	✓		Rear Window (Right)	✓	
Rear Window (Left)	✓		Rear Quarter Window (Left)	✓	
Rear Quarter Window (Right)	✓		Rear Window Wiper Switch	✓	
Windscreen Wipers Switch	✓		Wiper Blades Front & Rear	✓	
Power Window Controls	✓		Left Side Mirror	✓	
Right Side Mirror	✓		Outside Rear View Mirrors	✓	
Sun Visors, Vanity Mirror & Light	✓		Front End Exterior Lights (Left) - Headlight	✓	
Front End Exterior Lights (Right) - Headlight	✓		Side Exterior Lights	N/A	
Rear End Exterior Lights (Left) - Reverse, Taillamp, Stop	✓		Rear End Exterior Lights (Right) - Reverse, Taillamp, Stop	✓	
Hazard Lights	✓		Indicator Light	✓	
Fog Lamp Function	✓		Daytime Running Light	✓	
Low / High Beam Function	✓		Auto On / Off Lights	✓	
Spare Tyre	N/A		Jack & Tool Kit	✓	
Rims	✓		Wheel Alignment	✓	
Wheel Covers & Center Caps	✓				

Interior

Items	Status	Comments		Status	Comments
Radio / Cassette / CD / DVD Player	✓		Speakers	✓	
Alarm / Theft Deterrent System	✓		Reverse Camera	✓	
Antenna	✓		Air Conditioning Switch Panel	✓	
Air Conditioning Parts	✓		Air Conditioning System	✓	
Front Aircon Vents	✓		Rear Aircon Vents	✓	
Anti - Fog / Defroster Coil Damage	✓		Center Armrest / Console	✓	
Floor Mats	✓		Interior Carpet	✓	
Front Door Trim Board (Right)	✓		Front Door Trim Board (Left)	✓	
Door Trim Board 2nd Row (Right)	✓		Door Trim Board 2nd Row (Left)	✓	
A - Pillar Door Trim Board (Right)	✓		A - Pillar Door Trim Board (Left)	✓	
B - Pillar Door Trim Board (Right)	✓		B - Pillar Door Trim Board (Left)	✓	
C - Pillar Door Trim Board (Right)	✓		C - Pillar Door Trim Board (Left)	✓	
Glove Box	✓		Dashboard Drawer	✓	
Front Seat Including Electric Seat	✓		Rear Seat Including Electric Seat	N/A	
Folding Seats	✓		Hot / Warmed Seats	N/A	
Cooled Seats	N/A		Seat & Head Restraint Adjustment	✓	
Headlining	✓		Parcel Shelf / Speaker Board / Tonneau Cover	✓	
Clock	✓		Power Outlet - 12 V Port / Cigarette Lighter	✓	

Power Outlet - USB Port / Cigarette Lighter	✓		Power Steering	✓	
Steering Wheel Controls	✓		Steering Wheel Condition	✓	
Tilt / Telescopic Steering Wheel	✓		Tripmeter And Odometer	✓	
Interior Courtesy, Dome & Map Lights	✓		Ashtrays	N/A	
Handbrake / Footbrake Lever	✓		Gear Knob	✓	
Horn	✓		Warning Light	✓	
Cruise Control Operation	✓		Driver Profile/ Memory System	✓	
Dashboard / Control Panel	✓		Paddle Shifters	✓	
Safety Belts	✓		Airbags	✓	
Central Locking System	✓		Remote Boot Release	✓	
Push Start Button System	✓		Fuel Cap Release	✓	
Luggage Compartment Light	✓		Luggage Compartment Trim & Cargo Net	✓	
Luggage Board	✓				

Underbody And Under The Hood

Items	Status	Comments		Status	Comments
Brake Fluid	✓		Transmission Fluid	✓	
Transmission Fluid Leaks	✓		Power Steering Fluid	N/A	
Windshield Washer Fluids	✓		Engine Oil	✓	
Engine Oil Leaks	✓		Coolant Tank	✓	
Coolant	✓		Radiator	✓	

Wiring	✓		Engine Cover	✓	
Battery	✓		Exhaust System	✓	
Power Steering Pump	N/A		Rack And Pinion, Linkage & Boots	✓	
Tie Rods & Idler Arm	✓		Control Arms & Ball Joints	✓	
Sway Bars, Links & Bushings	✓		Front Tyre (Left)	✓	
Front Tyre (Right)	✓		Rear Tyre (Left)	✓	
Rear Tyre (Right)	✓				

Other information

Items	Notes	Notes
Inspection Summary	<p>1) Carro Care Inspection and/or Report, shall not be taken as a guarantee that the vehicle will remain in the same condition, as various factors and incidents later could contribute the deterioration/change on vehicle condition. 2) Inspection of vehicle condition includes, using of computerized diagnostic equipment strictly for measuring and checking of faultcodes, visual checks and road test. 3) Carro Care will only conduct road test no more than 60kph at a short distance. Any intermittent abnormalities such as noise, jerky, vibrations etc may not be able to detect / identify.</p>	